

USGS EL. 228.75

DESCRIPTION - Brass cap

Location - at the centerlines of Oro-Dam Blvd. and Myers St.

MONUMENT OK - covered w/ AC should RESET BRASS CAP IN COND RETURN  
WILL NOT BE ABLE TO EXPOSE IN NEW  
SURFACE.

B.M. #158