

USGS EL. 157.10

DESCRIPTION - nail in curb return

LOCATION - SW curb return at Montgomery St. add 5th Ave.

*MONU OK.*

B.M. #56